

Menu

HISTORY FILE MAP for year 2003

REALTIME

PLAYBACK


RECALLED REALTIME

RECALLED PLAYBACK

070.00:01-00:17 16m realtime data lost (8m 512bps & 8m 1024bps) due to late AOS at DSS-24. The station could not load predicts so a manual acquisition was performed. DR G102469 refers.

070.08:35-08:48 DSS-25 provided downlink due to DSS-24 maser failure. DR G102454 refers. 13m realtime data (7m 2048bps & 6m 512bps) lost since DSS-25 track ended earlier than the scheduled DSS-24 support.

074.04:49-05:53 4m 2048bps realtime and (073.19:25-19:35) 10m 512bps playback data lost due to a TLP problem at DSS-24. DR G102481 refers.



076.00:16-00:24 8m 512 bps realtime data lost due to long reacquisition after 1-way to 2-way transition at DSS-14. No DR raised

073.00:27-00:29 Bad data from DSS-14 resulted (072.21:16-21:21) in 2m 4096bps realtime and 12m (072.21:23-21:30) 512bps playback data. No DR raised.

(073.22:21-22:29) 8m 512bps playback data lost as tape recorder was switched from record to standby and back to record again while out of pass.